ATTACHMENT D

Notice of Alleged Safety or Health Hazards Mon Apr 14, 2003 4:16pm

Federal Correctional Institute		200381895
Site Phone (814) 362-8900		(814) 363-6811
P.O. Box 5000, Bradford, PA 16701		
Mail Phone (814) 632-8900		(814) 363-6811
Stephen Housier, Safety		(324) 303-0011
Federal Corrections		
9223	Primary NAICS	922140 st. Include the approximate number of
	Rt. 59 and Big Shanty Rd., I Site Phone (814) 362-8900 P.O. Box 5000, Bradford, P. Mail Phone (814) 632-8900 Stephen Housler, Safety Federal Corrections	P.O. Box 5000, Bradford, PA 16701 Mail Phone (814) 632-8900 Mail FAX Stephen Housler, Safety Telephone Federal Corrections Ownership

- 1. Ventilation is inadequate to control the hazards associated dusts generated during the production processes. These dusts include but are not limited to wood dust, particle board dust, and micore board dust.
- 2. Ventilation is inadequate to control the hazards associated with vapors that are produced by the glues utilized in the laminating processes.
- 3. Dust is accumulating on surfaces throughout the factory area. This dust includes but is not limited to wood dust, particle board dust, and micore board dust.
- 4. Personnel are smoking in close proximity to operations that produce wood dust and utilize flammable glues.
- Compressed air above 30 psi is being utilized for blow-downs and cleaning operations.
- . lexi-glass and plywood are being stored on top of electrical boxes. Electrical boxes are located in the back by the dock area.
- 7. Personnel are potentially exposed to a fire hazard from a heavy accumulation of scrap wood at the loading dock area.

LOCATION:

UNICOR Factory (Including but not Limited To):

- * Loading Dock Area
- * Saw Area
- * Laminating Area, Front Area by Office